



CE

Dear Customer

Thank you for purchasing this product.
For best possible performance and safety, please
follow these operating instructions carefully.

Use as Directed

This device serves exclusively to wind force meas-
urement.

General Precautions

Check this device for possible damages before every
use. If it shows visible damages, it may not be used
anymore. Consult your dealer for necessary repairs.
Never use this device close to inflammable or explo-
sive gases, fumes or dusts.

Do not try to disassemble the device.

Do not clean this device by using chemicals, ben-
zene or solvents.

Avoid sudden change of temperature, as this may
cause condensation inside the unit which may lead
to damage.

Do not dip the device under water.

Do not put the device under endurance stress.

- 8 -

©B

Avoid strong magnetic fields which may appear near
electric and electronic devices. Magnetic fields may
lead to unwanted display due to the magnetic sensi-
tivity of the Windmaster.

Use the Windmaster exclusively within the specified
ranges.

Avoid both strong vibrations and mechanical stress.

Notice

The type of battery used is not rechargeable. When
disposing of used batteries make sure you are in
accordance with your local refuse disposal and envi-
ronmental regulations.

Disclaimer of Warranty

Damages caused by ignoring these operating
instructions and also consequential damages will not
be warranted.

Alterations to specifications are subject to change
without notice.

WINDMASTER is a registered trademark of Kaindl
Electronic.
© Copyright 2001 by Kaindl Electronic.
2-9-1-2

- 9 -